ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	12	Shettihalli
Street ID	**Street Name**	**Significant Landmark**
W0134	1st Crs	Abbigere Surroundings
Segment No.	**Total Length (m)**	
12/S-W0134/S024737	156.46	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	156.46	77.529828	13.072094	77.531239	13.071796	Abbigere Main road	Dead end

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of dry waste center of Abbigere and other works in ward no-12 Shettyhalli Sub division	3000000	2019
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Others	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Construction of dry waste center of Abbigere and other works in ward no-12 Shettyhalli Sub division	012-19-000025
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/ /2019-20	01/02/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
29/10/2020	28/10/2021	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9945044476		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		AP Shivakumar
Date of Inspection	**Remarks**	
30/11/2020		

Category	Image	Photo Remark
Road Condition		Location was not determined.
Road Condition		Location was not determined.
Road Condition		Location was not determined.

Remarks

Designation	Approver Name	Date	Target Date	Remark

Zone: DASARAHALLI Ward No: 12 Ward Name: Shettihalli Street ID: W0134

Date: 30/11/2020 Time: 15:04:24 RH 20201130150424